

0020Z 05 JAN 63

SECRET

EDD

WER

KB

RLP

RDO

PAG

SAH

MD/OSA

OD/OSA

OD/OSA

INTEL/OSA

25X1A DIRECTOR

OSA/TCO (1-2-3-4-5-6-7-8) •

ROUTINE

TOR: 0428Z 05 JAN 63

IN 61363

25X1A

CITE

25X1A

25X1A

1. [] FOR INFO.

25X1A

2. FROM [] RE G3210. EVALUATION NOT COMPLETE BUT YOU HAVE PROBLEMS. FROM START OF MISSION POSITION 3R SHOWS HEAVY OVEREXPOSURE INDICATING SLOW SHUTTER. AT FRAME 401 SHUTTER FAILED TO OPEN AND REMAINED CLOSED ON 3R BALANCE OF MISSION. REPEAT THIS APPLIES TO POSITION 3R ONLY.

3. NEW SUBJ. ON 9L SIDE ON EVERY FRAME THERE IS PIN-HEAD MINUS DENSITY SPOT INDICATING POSSIBLE DIRT ON PLATEN. LOCATION IN LINE WITH INBOARD END OF POSITION INDICATOR AND ABOUT 2 1/2 INCHES FROM SAME.

4. CHIN UP AND HACKLES DOWN.

END OF MESSAGE

SECRET